


Solid Corner Return Avoids Delicate 45 Degree Mitres.



Plan View
Sanded Corner Return

→ = Down Slope

Kilkenny Blue Limestone.
 A compact bioclastic crinoidal Limestone, with a rich fossil content of mainly shells from brachiopods (shellfish) and coral.
 Flexural Strength 12.7 MPa
 Compressive strength 136MPa
 Density 2689 Kg/m³
 Water Absorption 0.1% dry mass

Chemical Composition,
 98% Calcite, 0.7% Dolomite,
 0.7% Quartz, 0.2% Organic Carbon, <0.1% Iron Sulphite.

Quarry Location, Threecastles Co. Kilkenny, R95 RF22. Ireland.

General Notes	
Limestone Corner Window Cill, Sanded return.	
Sanded finish.	
All Dimensions in Millimetres	
Our Limestone is quarried in our Threecastles Quarry, Co Kilkenny. It is Cut and Crafted in our Stoneryard in Stradbally Co. Laois.	
	
www.mckeonstone.ie E Mail, info@mckeonstone.ie Telephone (0) 578 625151 Stradbally, Co.Laois. R32 XH52.	
Project Name and Address	
McKeon Stone.	
Drawn by E.O'Malley	Sheet P1
Project Corner Return.	
Date 06/12/2019	
Scale Not to Scale	